

# Appendix A

## **Terminal Introduction**

The Air Carrier Terminal Building opened in February 1992. The terminal contains approximately 38,000 square feet of floor space on two levels. Approximately 29,300 square feet are on the main level which primarily supports airport administration, ticketing, hold rooms, bag claim, security, car rental, restrooms, public circulation, and waiting area. The lower level is approximately 8,600 square feet and primarily supports airline offices, hold rooms, restrooms, and circulation/public space. The terminal is supported by 16,000 square yards of apron that can accommodate a wide range of aircraft. An inventory of the passenger terminal has been documented based on a survey of existing conditions and interviews with the Airport Director, Deputy Airport Manager, Airport maintenance staff, airline station managers, the Transportation Security Administration (TSA) Supervisor, and personnel from the rental car agencies.

## **Terminal Requirements**

Facility requirements for the passenger terminal building are based on forecasts of peak hour activity (including originating and terminating passengers, baggage, and aircraft operations), application of industry standards, FAA planning guidelines (AC 150/5360-9 and 150/5360-13), and information gathered during the inventory process.

Based on the facility requirement analysis, the terminal facility will have excess capacity throughout the planning horizon. Approximately 24,200 square feet of facility will be required to accommodate demand by 2026. The existing terminal has 37,900 square feet of existing space available resulting in a surplus of approximately 13,700 square feet. The program areas for each major terminal function for each forecast year are presented in **Table 3** in the facility requirements chapter. Although the terminal has surplus space, some of the individual functional areas have become less efficient due to the new security requirements. The inventory has identified several areas that require additional analysis to address these efficiency issues. The airport development concepts will identify improvements to the passenger terminal facility.

## **Reference Images**

**Figure 1** – Upper Level Plan

**Figure 2** – Lower Level Plan

**Figure 3** – Deplaning Passenger & Admin. Expansion

**Figure 4** – Upper Level Baggage Screening Option

**Figure 5** – Lower Level Baggage Screening Option

**Figure 6** – Bag Claim Expansion Option


## **Curbside and Entry to Terminal**

Curbside access to the terminal appears sufficient for the landside activity. Curb cuts for ADA access into the facility are adequate and meet local and national standards. Entry areas into the terminal are adequate and allow easy access for passengers with their bags.

## **Ticketing Lobby**


The ticketing lobby was observed to be adequately illuminated, sufficient in floor area for processing the peak hour demand of passengers, based on original design. However, like many terminals since 9/11, the ticketing lobby now accommodates the passenger queuing space for ticketing as well as the TSA's explosive trace detection (ETD) processing stations. These ETD stations reduce the available queuing space for passengers waiting for ticketing, which was not designed for this activity. During the terminal survey, the two airlines (US Airways Express and Delta Connection), expressed concern over TSA's current methodology in screening passengers through the ETD process. Currently, passengers queue in between TSA ETD stations, which adds confusion as to where the ticketing line starts and

stops. Passengers initially queue, and then proceed through the ticketing process. Once ticketed, passengers are requested to proceed with their baggage in a reverse direction back through the queue to the ETD stations. A second queue in the same area as the ticketing queue is formed for ETD screening. The passenger then proceeds through the ETD screening and their bags are returned back to the ticket counter for loading onto the outbound conveyer. The back and forth movement is disruptive and confusing to the passengers. The airlines have requested a less confusing process to be developed.




**Partial Fig. 1 - Existing Ticketing and Bag Screen Queuing**

Alternative solutions to this process include: relocating the TSA to the front (adjacent to the ticket counter), potentially placing the ETD process behind the ticket counter (**Figure 4**), or conducting the ETD screening or inspection by other equipment types in the baggage make-up area (**Figure 5**). The airlines reported that they do not like the idea of sharing space behind the ticket counter with the TSA.



**Partial Fig. 4 - Upper Level Baggage Screening Option**



**Partial Fig. 5 - Lower Level Baggage Screening Option**

Ten percent or less of the passengers check-in online prior to arriving at the Airport. Delta installed self-serve kiosks in early 2008. The remainder of the airlines responded that self-serve kiosks were not needed at this time, as they are used to reduce staff and the current airlines' are already at minimum levels. The airlines reported that their airline ticket office (ATO) and operations office area were adequate. US Airways had a crew based at LYH, but has now given back most of the lower level operations space that they once leased. As a result, there is excess operations and office space currently available. Since United Express no longer serves LYH, there is available area for both ticketing and ticket office space for

a new entrant carrier. The airlines also reported that they will soon be adding scales to the ticket counter

baggage wells. There is not a specific time frame for relocating the TSA from the ticket queuing area. This project is contingent upon the availability of funds to provide the desired solution.

### **Restrooms**

Restrooms are in very good condition and meet both local and national Americans with Disabilities Act (ADA) standards, and are adequately sized for peak hour passenger levels.

### **Airport Administration Offices**

Airport administration offices are adequate for the staff currently housed at the terminal. The Airport is in the midst of a potential change to be under control of an Airport Authority. If this occurs, it is anticipated that another assessment of the office requirements would be needed.

### **Concessions**

Due to the recent ban on liquids allowed through the security checkpoint, the demand for coffee and food purchases dropped significantly. Vending machines are available just prior to passenger screening and at the lower holdroom. Retail concessions are not provided post security. The airlines and Airport personnel reported that passengers have complained about the lack of concessions. Employees at the terminal are now forced to go off-airport for meals.

### **Passenger Security Screening Checkpoint**

The TSA operates a single-lane security checkpoint with one walk thru metal detector (WTMD), one x-ray, and one secondary inspection area. The security checkpoint is manned to accommodate the first flight out in the morning (approximately 5:00 AM) until the last departing flight in the evening. The checkpoint is closed after the last flight. However, when the TSA has left after the last departing flight, passengers on arriving flights exit the sterile area with the use of a shunt button to open the locked door for exiting the secured area. TSA sweeps the secured area in the morning as a standard procedure. Currently, the TSA has an office area of approximately 1,100 square feet, close to the checkpoint, which provides adequate future space for the break room, training, and office needs.

The current TSA passenger screening rate for a single check-point lane is 200 passengers per hour. Based on the summary of aircraft operations and total passenger forecast shown in Table 35 in the forecast chapter, the largest forecast peak load is 243, which includes deplaning passengers. The forecast peak hour load for passenger screening will stay below the 200 passenger TSA rate per hour.

### **Passenger Departure Holdrooms**

Passenger flow to the active holdroom is awkward after proceeding through security, as the upper level holdroom, which is not used, is directly ahead and passengers must take an immediate right to access a stair, escalator, or elevator that leads to the lower level holdroom.

The upper level holdroom is not currently used and is reserved for future use as required. An exterior door exists for access to a future passenger loading bridge. As air service expands, this area can be utilized as an additional gate.

All aircraft are accessed through the lower passenger holdroom via ground level boarding. The holdroom has sufficient capacity to accommodate peak hour departing flights. Free wi-fi internet access is available and adequate restrooms serve the space.

A gate podium is located at the back portion of the holdroom which accommodates two carriers, and could accommodate three if necessary. The gate podium has some plastic laminate damage which is partially covered by a regulatory sign.

There are 64 seats in the holdroom area. In the future, if peak hour departures increase and the seating area needs to be increased, the gate podium could be moved to the back wall, as the space behind the gate podium is not used. This will allow more room for seating between the escalators.

The overall condition of the holdrooms is good. However, there are some deficiencies, which are described below. The floor finishes are a combination of rolled carpet and terrazzo. The ceiling and walls include acoustical ceiling tile and painted walls with rubber base. Recessed walk-off grates are installed at the doors.

Damage is evident below the edges of the window openings at both the upper and lower holdrooms. The drywall is cracked and appears to have been repaired repeatedly and continues to crack, which is possibly due to condensation. The joint between the exterior window sill and wall has been recaulked. The wall base on the upper level is in poor condition. The base is discolored and spider cracks are visible throughout. The base at the lower level holdroom is in much better condition and may have been replaced at some point.




**Damage at Holdroom Window Sills**

The overall condition of the acoustical tile ceiling in the holdrooms is good, other than a couple of areas. The ceiling tiles are not in as good condition at the back portion of the lower holdroom by the elevator and employee access door. Water stains have formed on the acoustical ceiling tile outside of the Men's restroom on the upper level below HVAC unit AC-5. Roof and window weather-proofing should be inspected in greater detail to determine the cause of the water infiltration.



**Water Damage at Holdroom Ceiling**

**Deplaning Passengers**




**Partial Fig. 1 – Existing Passenger Screening & Deplaning Corridor**

The original design of the terminal allowed for the entire width of the connecting bridge between the terminal and the holdrooms to be utilized for enplaning and deplaning passengers. Current TSA security operation occupies the majority of the bridge for passenger screening, which impacts the available circulation space for deplaning passengers. After deplaning and ascending up the escalator, the passengers encounter a wall and have to turn immediately to the left to enter a narrow single-file passageway to reach the non-secure side of the terminal. This exit flow should be improved to be more straightforward.

An option for improving the flow for deplaning passengers would be a 200 s.f. (approx. 9' x 22') expansion to the side of the connecting bridge and a 1,000 s.f. (approx. 29' x 35') expansion to the


administration suite (**Figure 3**). This modest expansion would provide a logical deplaning corridor, increase passenger flow and will provide additional space for passenger screening. Although it would be necessary to displace a portion of the airport administration suite to accommodate this expansion, the admin. Expansion would include the displaced area. To address the displaced administration area the conference area within the administration suite would be divided in half, providing two offices and a 950 s.f. (approx. 28' x 34') expansion to the end of the suite to provide an adequately sized conference room. There is not a specific time frame associated with implementing this improvement; it would be up to the airport to determine based on the availability of funds.



**Partial Fig. 3 – Deplaning Expansion**

**Baggage Claim**

All aircraft are ground-loaded regional aircraft and many passengers claim their gate-checked baggage next to the aircraft on the apron before entering the building. Delivery time to the bag claim device is very short. The baggage claim area appears adequate for the current peak hour passenger demand. The



**Partial Fig. 6 - Bag Claim Expansion**

projected peak hour deplanement notes an increase through 2026 (**Table 25** in the forecast chapter). The number of passengers checking bags varies from 50-75%. For evaluating the bag claim area, it is assumed that 65% of deplaning passenger will check bags at the peak hour. This is a conservative figure, as the current bag fees may result in fewer checked bags. Per the forecast, the bag claim device is anticipated be 15% over capacity by 2011. If the bag claim device is expanded (**Figure 6**), it will have sufficient capacity through 2026. Another scenario that may result in an increase in bag claim device capacity is if narrow body service were to serve LYH. The expansion shown in Figure 6 utilizes available open space, would not negatively impact the ready/return lot adjacent to the terminal and would not require a terminal expansion. One concession that would need to be made is the loss of the display area in that part of the terminal.

**Rental Cars and Ground Transportation**

LYH is well-served by several rental car companies. The rental car companies reported that they have adequate office area and counter space. However, they requested the need for a larger ready/return lot

adjacent to the terminal. Hertz, which has the largest market share at LYH, indicated that not having enough spaces requires juggling of cars to keep the lot useable for their operation.

There is a limousine taxi service counter which provides good service. Improved signage and the installations of phone kiosks to alternative taxi/limo service would be helpful to passengers who may desire other choices of transportation

### **Maintenance and Energy Efficiency**

The Airport is in the midst of potentially transitioning from a City of Lynchburg Department to an Airport Authority authorized by the State of Virginia. This agency status change could affect operations and maintenance implications for the terminal and other facilities on the Airport. For example, many contracts that are currently awarded and administered through the City of Lynchburg may or may not be assessed on the same level of value as an Airport Authority assessment. Therefore, when the Airport transitions to an Airport Authority, electrical rates may increase substantially. This is also true for maintenance and other ongoing agreements which could be affected.

It was observed that lighting in the lobby and concourse was on at full intensity on a very sunlit day. Photometric or timed lighting controls and utilizing T-12 fluorescent light fixtures would reduce the energy usage for lighting in the terminal substantially, saving the Airport from a higher energy bill. This can also be viewed as a positive public relations model, an example of providing a sustainable environment.

The standing seam metal roof and surrounding trim is in need of repair. The white perimeter of the roof is in need of new paint and numerous rust spots are visible throughout the metal roof panels. Funds should be budgeted for repair or replacement. No roof leaks were evident relative to the metal roof panels at this time. HNTB's recommendation is to have a roof professional evaluate the panels to determine whether the rust spots could be repaired and when a new roof would likely be required.



It was reported from time to time that the escalators are inoperable and passengers must walk up and down the stairs or take the elevator. From conversations with manufacturers and service providers, the escalators may be nearing the end of their useful life. For the immediate future it may be cost effective to upgrade the motor control components and refurbish or replace when the cost or frequency of repairs escalates. The escalators currently run continuously throughout the day, even at off-peak times. Incorporating motor control kits for escalators, such as Kone's EcoStart™, saves energy and extends motor life. If it is determined the escalators need replacing in the near future, a viable option may be Kone's ECO MOD. This system offers many advantages over a full replacement. It works within the existing building structure and the parts are brought to the site in crates and it will not require special crane hoisting or building façade removal. In order to determine the best course of action an escalator professional should be brought on site to evaluate the existing equipment.

The fire alarm control panel is currently malfunctioning. Client has been told that parts are no longer available for the existing system. The system also sends a false alarm "downtown" when the power goes out.

It is in the Airport’s best interest to update the HVAC equipment as soon as financially feasible and implement energy-saving strategies to prepare and position for future rate increases on the O & M budget. For example, the HVAC system is an all electric system and has outlived its expected life of service (2003 ASHRAE HVAC Applications - Table 3). It may be cost-effective to replace the older equipment with modern energy-efficient systems to reduce the impact of rising O & M costs. Natural gas is available “capped off” at the terminal. Indirect gas heat should be considered when the roof top unit replacement design is performed. First cost will be higher than an all electric unit. However, electricity rates are predicted to increase faster than natural gas rates by the U.S. Dept. of Energy. Therefore, gas heat may be the most cost effective heating source.

The six roof top units are electric cooling units with air cooled condensers and electric heat. There is one 50 ton unit, one 40 ton unit, three 25 ton units and one 20 ton unit. These units are over 16 years old and have reached their useful life. According to brief discussions with the equipment maintenance personnel, these units are starting to cost a significant amount of time and money to keep operating. Some of the things that are being replaced on significant intervals are motor and fan bearings, electrical components and control components. In addition, refrigeration compressors have required replacement/rebuilding. The airport recently spent \$50,000 on HVAC to update the damper control on the HVAC units. Although our conversation was more of an overview in nature and the equipment maintenance personnel could not provide an annual maintenance amount at the time, HNTB estimates that the Airport may be spending as much as \$53,000 per year, or more, to keep the units running given the nature of the repairs that are being required on a frequent basis. Six brand new units might be expected to cost less than \$10,000 per year to perform routine maintain tasks.

Replacement cost of the 6 existing units is estimated to be approximately \$400,000. This cost includes equipment removal, equipment installation, roof repair, electrical modifications/connections and is based on Contractor's expected cost plus 25% overhead and profit. It does not include any other costs such as project soft costs including A&E design fees, general requirements, sales tax, Client administrative costs, permits, or any other fees.

Potential savings based on annual maintenance costs is estimated to be approximately \$43,000 per year so a simple payback based solely on the costs described above may be in the range of nine to ten years. It should be noted however that the annual maintenance costs will continue to increase as the existing units continue to age and there will come a time when the units simply become non-repairable and require replacing in any case, so annual maintenance costs should not be used as the sole metric when deciding to replace the units. There are other less tangible costs such as impacts on airport operations while the units are down for repair or in the event that one fails suddenly and needs to be replaced because it has become non-repairable. These issues also need to be considered.

**Terminal Aesthetics**

The overall appearance of the terminal is relatively current and not dated. The incorporation of brick at the interior has helped the terminal age well and the terrazzo flooring is long lasting and is visually appealing. The ticket counter area would be the primary area in need of updating and freshening up. The HVAC grilles high on the back wall of the ticketing area are in need of cleaning and the fins that direct air flow need to be angled identically for a uni-



**Ticket Counters**



**Ticket Lobby**



form appearance. The ticket queuing area would be fine as it is if the bag screening could be relocated. The ticket counters are showing wear and the is damaged in areas. An updated ticket counter area, new ticket counters and moving the bag screening operation out of the ticket lobby would positively impact the passenger experience.

### **Terminal Sustainability Ideas**

Depending on the premium the Airport is willing to invest for sustainability goals, there are several ideas that could be incorporated into the terminal in a master plan CIP. The energy and efficiency gains for some specific items will have a reasonable return on investment, but many other sustainability goals will come at a cost to the bottom line budgeted of the Airport. It is important that the Airport establish the intent and premium amount they intend to invest in their CIP. For example, the first priority of sustainability elements should be the ones that come with a quick “return on investment” (ROI). The Airport could establish a cap of “x” amount of dollars per year in its CIP for the “nice to have” sustainability items knowing they would receive some political and positive press in the community, while acknowledging the ROI may not be realized.

#### **Short-term ROI:**

1. Lighting controls
2. Efficient T-12 fluorescent light fixtures and other efficient fixtures
3. Baggage conveyor belt systems that “time-out” quickly after use
4. Motor control kits for escalators
5. Low-flow and automated toilet and lavatory fixtures
6. Electrical charging stations for electrical GSE equipment
7. Recycling center in terminal
8. Recycled building materials on site work and building projects


#### **Medium-term ROI:**



1. Replacement of HVAC equipment
2. Day-lighting strategies/clerestories
3. Solar shading devices
4. Solar hot water panels
5. Geo-exchange heat pumps


#### **Long-term ROI:**


1. Solar photovoltaic panels for power generation
2. Reduction of storm water run-off



\* Master Plan Update: Chapter One - Forecasts














Figure 6 - Bag Claim Expansion Option

# Appendix B



# ILS or LOC RWY 4





LYNCHBURG RGNL/PRESTON GLENN FIELD (LYH)

LOC I-LYH <b>110.1</b>	APP CRS <b>036°</b>	Rwy Idg <b>6800</b> TDZE <b>906</b> Apt Elev <b>938</b>
---------------------------	------------------------	--

**▽** \* DME REQUIRED  
**▲** \*\* RVR 1800 authorized with the use of FD or AP or HUD to DA.

**MALSR**  
 MISSED APPROACH: Climb to 1800, then climbing right turn to 3500 via heading 080° and LYH VORTAC R-053 to SWARM Int and hold.

ATIS <b>119.8</b>	ROANOKE APP CON <b>135.0 254.32</b>	LYNCHBURG TOWER ★ <b>127.65 (CTAF) 0 257.8</b>	GND CON <b>121.9</b>	UNICOM <b>122.95</b>
----------------------	--	---	-------------------------	-------------------------



Remain within 10 NM	BOJAR INT/LOM	1800	3500	SWARM
3000	LELYE LYH 3.8	2098		△
GS 3.00° TCH 58	*2900			* LOC only.
	2900	*2200		
	4 NM	3.6 NM		
CATEGORY	A	B	C	D
S-ILS 4		** 1106/24	200 (200-½)	
S-LOC 4	1320/24	414 (400-½)	1320/40	414 (400-¾)
CIRCLING	1640-1 702 (800-1)	1700-1¼ 762 (800-1¼)	1800-2½ 862 (900-2½)	1800-2¾ 862 (900-2¾)

NE-3, 07 MAY 2009 to 04 JUN 2009

NE-3, 07 MAY 2009 to 04 JUN 2009

# RNAV (GPS) RWY 4

LYNCHBURG RGNL/PRESTON GLENN FIELD (LYH)

WAAS CH <b>58205</b> <b>W04A</b>	APP CRS <b>036°</b>	Rwy ldg <b>6800</b> TDZE <b>906</b> Apt Elev <b>938</b>
--	------------------------	---


MALSR



MISSED APPROACH: Climb to 3500 direct JIXOX and via 075° track to SWARM and hold.


**▼** For inoperative MALSR, increase LNAV Cat A and B visibility to RVR 5000. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C (4°F) or above 47°C (116°F). DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA.

ATIS <b>119.8</b>	ROANOKE APP CON <b>135.0 254.32</b>	LYNCHBURG TOWER ★ <b>127.65 (CTAF) 0 257.8</b>	GND CON <b>121.9</b>	UNICOM <b>122.95</b>
----------------------	--	---	-------------------------	-------------------------




NE-3, 07 MAY 2009 to 04 JUN 2009

NE-3, 07 MAY 2009 to 04 JUN 2009



CATEGORY	A	B	C	D
LPV DA		1176/40	270 (300-¾)	
LNAV/VNAV DA		1395/60	489 (500-1¼)	
LNAV MDA	1400/40	494 (500-¾)		1400/50 494 (500-1)
CIRCLING	1640-1 702 (800-1)	1700-1¼ 762 (800-1¼)	1800-2½ 862 (900-2½)	1800-2¾ 862 (900-2¾)



# RNAV (GPS) RWY 4

# RNAV (GPS) RWY 22




LYNCHBURG RGNL/PRESTON GLENN FIELD (LYH)

WAAS CH <b>97705</b> <b>W22A</b>	APP CRS <b>216°</b>	Rwy ldg <b>7100</b> TDZE <b>938</b> Apt Elev <b>938</b>
--	------------------------	---

**⚠** For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C (4°F) or above 47°C (116°F). DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA.

**MISSED APPROACH:** Climb to 3000 direct KUCEC and via 207° track to LYH VORTAC and hold, continue climb-in hold to 3000.

ATIS <b>119.8</b>	ROANOKE APP CON <b>135.0 254.32</b>	LYNCHBURG TOWER ★ <b>127.65 (CTAF) 0 257.8</b>	GND CON <b>121.9</b>	UNICOM <b>122.95</b>
----------------------	--	---	-------------------------	-------------------------



CATEGORY	A	B	C	D
LPV DA		1250-1	312 (400-1)	
LNAV/VNAV DA	1939-2	1001 (1100-2)	1939-3	1001 (1100-3)
LNAV MDA	1720-1 782 (800-1)	1720-1 ¼ 782 (800-1 ¼)	1720-2 ¼ 782 (800-2 ¼)	1720-2 ½ 782 (800-2 ½)
CIRCLING	1720-1 782 (800-1)	1720-1 ¼ 782 (800-1 ¼)	1800-2 ½ 862 (900-2 ½)	1800-2 ¾ 862 (900-2 ¾)

HIRL Rwy 4-22  
 MIRL Rwy 17-35  
 REIL Rwy 17, 22 and 35

NE-3, 07 MAY 2009 to 04 JUN 2009

NE-3, 07 MAY 2009 to 04 JUN 2009

# RNAV (GPS) RWY 22

# VOR RWY 4

LYNCHBURG RGNL/PRESTON GLENN FIELD (LYH)




VORTAC LYH	APP CRS	Rwy Idg	6800
109.2	026°	TDZE	906
Chan 29		Apt Elev	938

**▼** For inoperative MALSR, increase S-4 Cat A and B visibility to RVR 5000. Visibility reduction by helicopters NA.





**MISSED APPROACH:** Climb to 2000 via LYH VORTAC R-026 then climbing right turn to 3500 via heading 095° and LYH VORTAC R-053 to SWARM Int and hold.

ATIS <b>119.8</b>	ROANOKE APP CON <b>135.0 254.32</b>	LYNCHBURG TOWER ★ <b>127.65 (CTAF) 0 257.8</b>	GND CON <b>121.9</b>	UNICOM <b>122.95</b>
----------------------	--	---	-------------------------	-------------------------



NE-3, 07 MAY 2009 to 04 JUN 2009

NE-3, 07 MAY 2009 to 04 JUN 2009



CATEGORY	A	B	C	D
S-4	1400/40	494 (500-¾)		1400/50 494 (500-1)
CIRCLING	1640-1 702 (800-1)	1700-1¼ 762 (800-1¼)	1800-2½ 862 (900-2½)	1800-2¾ 862 (900-2¾)

# VOR RWY 4

ELEV 938	Rwy 4 Idg 6800'
TDZE 906	
Knots	60 90 120 150 180
Min:Sec	3:54 2:36 1:57 1:34 1:18

LYNCHBURG, VIRGINIA

AL-499 (FAA)






VORTAC LYH	APP CRS	Rwy ldg	<b>7100</b>
<b>109.2</b>	<b>207°</b>	TDZE	<b>938</b>
Chan <b>29</b>		Apt Elev	<b>938</b>

# VOR/DME RWY 22

LYNCHBURG RGNL/PRESTON GLENN FIELD (LYH)

		MISSED APPROACH: Climb to 2900 direct LYH VORTAC and hold.	
--	--	---	--

ATIS <b>119.8</b>	ROANOKE APP CON <b>135.0 254.32</b>	LYNCHBURG TOWER ★ <b>127.65 (CTAF) 0 257.8</b>	GND CON <b>121.9</b>	UNICOM <b>122.95</b>
----------------------	--	---	-------------------------	-------------------------



CATEGORY	A	B	C	D
S-22	1740-1 802 (900-1)	1740-1¼ 802 (900-1¼)	1740-2¼ 802 (900-2¼)	1740-2½ 802 (900-2½)
CIRCLING	1740-1 802 (900-1)	1740-1¼ 802 (900-1¼)	1800-2½ 862 (900-2½)	1800-2¾ 862 (900-2¾)

LYNCHBURG, VIRGINIA  
Amdt 8B 08269

LYNCHBURG RGNL/PRESTON GLENN FIELD (LYH)  
37°20'N - 79°12'W  
**VOR/DME RWY 22**

HIRL Rwy 4-22  
MIRL Rwy 17-35  
REIL Rws 17, 22 and 35

NE-3, 07 MAY 2009 to 04 JUN 2009

NE-3, 07 MAY 2009 to 04 JUN 2009

# Appendix C

Lynchburg Regional Airport  
Vehicle and Equipment List

EMIS	Vehicle / Equipment List	Vehicle / Equipment Use
1264	1980 Idaho Norland Snow Blower (Vehicle 12)	<b>OUT OF SERVICE</b>
2954	2007 GMC Sierra 2500 4x4 Pickup with snow plow (Vehicle 5)	Airport operations / maintenance and <b>snow removal</b>
5366	2005 New Holland Tractor (Model TC33D) (Tractor 10)	Airfield and terminal mowing
2728	2003 New Holland Tractor (Model TN70D) (Tractor 9)	Airfield mowing
5397	2007 John Deere Tractor with front end loader and broom (Model 6715) (Tractor 8)	Airfield mowing and <b>snow removal</b>
5281	2001 John Deere Mower	Terminal mowing
2473	1999 Ford Explorer 4x4 SUV (Vehicle 7)	Airfield operations / maintenance and <b>snow removal supervision / friction testing</b>
2599	2001 GMC C7500 (2-Ton) Dump Truck with snow plow and salt spreader (Vehicle 11)	Grounds maintenance and <b>land side snow removal</b>
5264	2000 Oshkosh 4x4 Multipurpose (H-Series) Vehicle with 18 foot broom / 22 foot plow / snow blower attachment (Sweepster) (Vehicle 16)	<b>Snow removal</b>
5265	2000 Oshkosh 4x4 Heavy Duty (P-Series) with snow plow and sand spreader (Schmidt) (Vehicle 17)	<b>Snow removal</b>
2730	2003 International Truck (Model 7400) 2000-Gallon runway deicer with snow plow (Tyler) (Vehicle 14)	<b>Snow removal</b>
2653	2002 GMC 4x4 (1-Ton) Truck with snow plow (Vehicle 4)	Grounds maintenance and <b>snow removal</b>
2734	2003 Chevrolet S-10 Pickup (Vehicle 6)	Custodial maintenance and airfield operations / maintenance
2736	2003 Ford Taurus (Vehicle 18)	Airport administration
2944	2007 Ford Explorer (Vehicle 9)	Airport police

# **Appendix D**

**(Halfsize ALP Set to be included in final document)**



# **Appendix D1**


**(Halfsize drawings to be included in final document)**

# Appendix E



# Appendix F

# ***NOTICE OF PUBLIC WORKSHOP***



## **LYNCHBURG REGIONAL AIRPORT**

### **AIRPORT MASTER PLAN UPDATE**

This notice is to announce the availability of a draft plan for future development at Lynchburg Regional Airport (LYH) as part of an update to the airport's master plan, and to invite airport users and the public to a workshop to review the plan and provide input in an open-house environment.

**Date:** Monday, June 8, 2009  
**Time:** 6:00 p.m. – 7:30 p.m.  
**Location:** Commission Conference Room  
Passenger Terminal  
Lynchburg Regional Airport  
4308 Wards Road  
Lynchburg, VA 24502

The City of Lynchburg is updating its master plan for Lynchburg Regional Airport for the purpose of planning for future capital needs at the airport in order to meet future aviation and user demand. A master plan is required by the Federal Aviation Administration for all airports that receive federal funding for eligible capital improvements.

For more information, please contact Lynchburg Regional Airport at: [airport@lynchburgva.gov](mailto:airport@lynchburgva.gov) or call 434-455-6090.

**NOTICE OF PUBLIC WORKSHOP**



**LYNCHBURG  
REGIONAL  
AIRPORT**

**AIRPORT MASTER PLAN UPDATE**

This notice is to announce the availability of a draft plan for future development at Lynchburg Regional Airport (LYH) as part of an update to the airport's master plan, and to invite airport users and the public to a workshop to review the plan and provide input in an open-house environment.

Date: Monday, June 8, 2009  
Time: 6:00 p.m. - 7:30 p.m.  
Location: Commission Conference Room  
Passenger Terminal  
Lynchburg Regional Airport  
4308 Wards Road  
Lynchburg, VA 24502

The City of Lynchburg is updating its master plan for Lynchburg Regional Airport for the purpose of planning for future capital needs at the airport in order to meet future aviation and user demand. A master plan is required by the Federal Aviation Administration for all airports that receive federal funding for eligible capital improvements.

LYNCHBURG REGIONAL AIRPORT  
MASTER PLAN  
PUBLIC MEETING  
JUNE 8, 2009

NAME	ADDRESS	PHONE OR EMAIL
DONALD BLEWIS	51 JAMESWOOD CT Forest	5215-2494
Steve Cuppy	1820 Clayton Ave Lynchburg, 24503 VA	434-426-0980